



JXMODEL


# JXmodel F2000

4X2 1/14 SCALE R/C




# 推荐工具

## RECOMMENDATION TOOL



内六角螺丝刀 十字螺丝刀

HEX DRIVERS 1.5MM 2.0MM 2.5MM




尖嘴钳

LONG NOSE PLIERS



套筒(原厂配有)

WRENCH 2.0MM



十字套筒

CROSS WRENCH


## 安装提示

### TIPS FOR ASSEMBLY

- 合金工艺制品存在一定的毛刺瑕疵属正常现象，用户需自行打磨  
IT IS NORMAL THAT THERE ARE SOME BURR DEFECTS IN ALLOY PROCESS PRODUCTS. USERS NEED TO POLISH THEM BY THEMSELVES
- 合金制品表面经打沙处理，用户涂装前先清理好产品上的油污、尘埃  
THE SURFACE OF ALLOY PRODUCTS SHALL BE SANDED, AND THE OIL AND DUST ON THE PRODUCTS SHALL BE CLEANED BEFORE COATING
- 合金制品涂装建议先喷环氧底漆、或者金属模型水补土油漆，再上色漆  
IT IS RECOMMENDED TO SPRAY EPOXY PRIMER OR METAL MODEL WATER PAINT BEFORE PAINTING ALLOY PRODUCTS
- 使用好质量的螺丝刀，避免磨损螺丝头  
USE GOOD QUALITY HEX DRIVERS TO AVOID STRIPPING SCREW HEADS
- 当将金属螺丝拧进金属部件时，请使用螺纹胶  
USE THREAD LOCK WHEN PUTTING METAL SCREWS INTO METAL PARTS
- 不要将螺丝拧太紧，否则将会磨损螺纹  
DO NOT OVER TIGHTEN SCREWS OTHERWISE YOU MAY STRIP THE THREAD


# 1 JXmodel

M3X6半圆头  
x8




# 2 JXmodel

- M2x6杯头 x8
- M3X5半圆头 x8
- M3x6半圆头 x4
- MP-11 x2
- MP-38 x1
- MP-39 x2
- MP-40 x1





# 3 JXmodel


- MP-12 x2
- H-A0024 x2




# 4 JXmodel


 2mm E型卡簧  
x2

 H-A0023  
x2





# 5 JXmodel


 MP-13  
x4


 MP-14  
x2

 MP-15  
x4

 MP-F1  
x2


 MP-F2  
x2


 MP-14  
x2




!此零件装配2组


# 6 JXmodel


 M2防松螺母  
x8


 MP-17  
x2





# 7 JXmodel

 2mm E型卡簧  
x2






 M3x14mm半圆头  
x2


 M3防松螺母  
x2

 H-A0023  
x2








# 8 JXmodel

-  M3x5半圆头  
x4
-  M3x6半圆头  
x1
-  M3x10半圆头  
x1
-  M3x12半圆头  
x1
-  x1 MP-18





# 9 JXmodel

-  M2x6杯头  
x8
-  M2x6平头  
x16
-  x4 MP-20
-  x4 MP-21




# 10 JXmodel

 2mm E型卡簧  
x2




x2 MP-22





x2 H-A0022

!注意安装方向  
此处为双层钢板





# 11 JXmodel


 M2.5塞打螺丝  
x4



## 12 JXmodel


 M2防松螺母  
x8


 x2 MP-23




## 13 JXmodel


 x4 M3x27杯头


 x2 M3x6扁头十字

 起步齿轮




## 14 JXmodel

 M3x5半圆头  
x4

 x1 MP-24


! 加注螺纹紧固剂  
M3x5mm半圆头






# 15 JXmodel

M3x8半圆头  
x4




M3x8mm半圆头  
! 加注螺纹紧固剂




# 16 JXmodel

M2x5半圆头  
x4




MP-26




# 17 JXmodel

M3x4机米螺丝  
x4





# 18 JXmodel



# 19 JXmodel


M3x9mm半圆头


 M3x9mm半圆头  
x2




# 20 JXmodel

M3x4mm扁十字头


 M3x4mm扁十字头  
x2

 x1 MP-27




## 21 JXmodel

M3x4扁十字头  
x8




x1 MP-28




## 22 JXmodel

M3x6半圆头  
x3







## 23 JXmodel

M3x5半圆头  
x2





# 24 JXmodel

-  M2x5半圆头  
x3
-  M2螺母  
x3



# 25 JXmodel

-  M2x5半圆头  
x4






## 26 JXmodel

M2x5半圆头  
x4

M2x8半圆头  
x8

M2螺母  
x4




## 27 JXmodel

! 建议涂装颜色  
透明黄 透明红 透明


! 胶水粘合

M2x5半圆头  
x4





## 28 JXmodel

M2x5半圆头  
x4









# 29 JXmodel

-  M3x16半圆头
- x4





# 30 JXmodel


-  M3x5半圆头
- x2
-  M3x6半圆头
- x2
-  M3防松螺母
- x2





# 31 JXmodel

-  M2x10杯头
- x20
-  M2螺母
- x20



! 后轮组件装配示意图




### 32 JXmodel





### 33 JXmodel



! 前轮组件装配示意图




### 34 JXmodel






# 35 JXmodel



MP-38  
M3x75十字  
x1




M3防松螺母  
x1







# 36 JXmodel



M2x10平头  
x4








# 1 JXmodel




x12

M2x4平头内六角



# 2 JXmodel


! 注意孔位方向



### 3 JXmodel

—  
x12


M2x12平头内六角



### 4 JXmodel

—  
x10

M2x4平头内六角



# 5 JXmodel



x5  
M3x12 半圆头内六角




M3防松螺母  
x5

M3x12mm半圆头

CX-07

M3防松螺母



# 6 JXmodel

M2x12外六角

x16

M2螺母

x14




x2 CX-08



x1 CX-09




x1 CX-10



# 7 JXmodel



CX-11

x33




M2x4十字头  
x20

CX-13  
x10




!注意合页装配方向  
对称装配  
共装配5组栏板


CX-14  
x10



# 10 JXmodel



# 11 JXmodel





# 12 JXmodel




x8

M3x5半圆头



x4 CX-18




# 13 JXmodel



x2

M3x5半圆头




# 14 JXmodel




x2

M3x5半圆头




# 15 JXmodel

<b>MAN</b> ①	
41-464	19-603
41-464	19-603
26-414	② 19-293
26-414	③ 19-293
19-453	19-364
19-453	19-364
SILENT	JXMODEL
SILENT	④ SILENT



# 16 JXmodel

<b>MAN</b> ①	
41-464	19-603
41-464	19-603
26-414	② 19-293
26-414	③ 19-293
19-453	19-364
19-453	19-364
SILENT	JXMODEL
SILENT	④ SILENT





JXMODEL

**F2000**